


Supply Issues – AN/TPS-59 Radar and AN/TPS-63 Radar




Pat Hugya, MARCORLogBases, Hugyapa@matcom.usmc.mil




AN/TPS-59(V)3 Antenna Parts

- Transmitter – 5840-01-152-1945
 - Approx 80 Repaired Per Year
 - Exchange Price \$87,278
 - New procurement with Lockheed Martin for 102 each. Delivery expected to begin in 12 months.
- Power Supply – 6130-01-146-8105
 - Approx 40-60 Repaired Per Year
 - Exchange Price \$31,139
- Receiver – 5840-01-147-9458
 - Approx 50 Repaired Per Year
 - Exchange Price \$60,848
- \$5.4 Mil funded in FY 02 for SDR Repairs of the above three items




SI-07751B-14/1B Vendor Level Maintenance for Line Replaceable Units of Radar Set, An/TPS-59(V)3

- Instructions for facilitating turn-in of 34 LRUs located in the Electronics Shelter
- WIR not MRP to be submitted through WOLPH or other means
- Carcass is shipped directly to the OEM, not MAB or MBB and not DRMO
- Limited spares available



AN/TPS-63(B) Radar Issues

- CFA Tube – 5960-01-035-1260
 - New procurement contract to be awarded mid August 2002 with delivery to commence in 5 months
 - Old Tubes to be sent to DRMO, they are not repairable
- 4 Radars scheduled for rebuild
 - Complete Sept 02; Jan 03; Apr 03; Jul 03
 - Issue will be based current needs



QUESTIONS?
